



abc laboratories

### T05 - One Point Thermometer Calibration Check

1. Pour approximately 150mL of distilled water into a beaker.
2. Place the reference thermometer into the beaker and let it sit for 3 minutes.
3. Place the multimeter into the water and wait for temperature reading to stabilise.
4. Record reference thermometer reading and multimeter reading into your **pH Meter Calibration and Maintenance Record** table.